





PL 23747

WVA No. : 23747



THK : 19.7 mm

VOLKSWAGEN

- MULTIVAN Mk V (7HM, 7HN, 7HF, 7EF, 7EM, 7EN), 04/03 -
- MULTIVAN Mk VI (SGF, SGM, SGN), 04/15 -
- TRANSPORTER / CARAVELLE Mk V Bus (7HB, 7HJ, 7EB, 7EJ, 7EF, 7, 04/03 TRANSPORTER / CARAVELLE Mk VI Bus (SGB, SGG, SGJ), 04/15 -
- EUROVAN V Bus (7HB, 7HJ, 7EB, 7EJ, 7EF), 04/03 -
- TRANSPORTER Mk V Box (7HA, 7HH, 7EA, 7EH), 04/03 -
- TRANSPORTER Mk V Platform/Chassis (7JD, 7JE, 7JL, 7JY, 7JZ,, 04/03 -)
- TRANSPORTER Mk VI Box (SGA, SGH), 04/15 -
- TRANSPORTER Mk VI Platform/Chassis (SFD, SFE, SFL, SFZ), 04/15 -



TEVES



- 1 INNER PIECE WITH WITHOUT WEAR INDICATOR WIRE
- 1 INNER PIECE WITH WITH WEAR INDICATOR WIRE
- 2 OUTER PIECES

- OE REF:**
- AUDI**
 - 7H0698151
 - 7H0698151A
 - SEAT**
 - 7H069815
 - 7H0698151A
 - SKODA**
 - 7H0698151
 - 7H0698151A
 - VOLKSWAGEN**
 - 7H0698151
 - 7H0698151A